


304554 2/8





F18me 2

304554 3/8 -3,96 2 PLC Ultrasonically Welded Wire Retention Area 50 After U-S operation to hold SRE (Rear) Fan wires on new rotor Alternator Front for both views tisue for New Rotor Before U-S operation to hold SRE (Rear) Fan wires on new rotor tisme 3 3.6 4.9 -2 PLACES . Og

Fisue 8 The state of the s -1.6 A - 2 PLACES -3.0 A · 2 PLACES -3.9 - 2 PLACES STRIP LEAD FOR DISTANCE SHOWN - 2 PLACES_ VIEW OF SLIP RING BEFORE FURNING LENDS . 63,3 . 59,3 44.0 2 PLACES -20.3 20.0 REF | 37.4 2 PLACES --Ø 14.85 14.55 REF 2 PLACES -Tet. Ø 8.48 8.40 REF

DP 304554 4/8 Views showing connection of Slip Ring & Coil





View of New Rotor

DP 304554 7/8

4. sue 15

